



HSM USB Serial Driver Release 3.5.35 contains (January 2023):

- Driver Version 2.1.6.41
- Includes embedded VC++ 2010 Redistributable
- Microsoft Certified

Supporting devices:

- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)
- Voyager -1250
- Hyperion 1300
- Industrial Area -Imaging Scanner
- Industrial Charge & Communication Base (CCB02)
- Honeywell N5600 Series Area Image Engine (PID_0974 is added)
- Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g



- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine



- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C
- Granit XP 1990iSR Area-Imaging Scanner
- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner
- Honeywell HF680
- Honeywell HH490 Hand-Held Scanner



- Genesis XP 7680GSR Presentation Scanner
- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)
- Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU)
- Honeywell HF521
- Honeywell LTSB N4680 (Win10 WHQL passed)
- Honeywell 20H2 N4680 (Win10 WHQL passed)
- Added Win7/8 versions supported, pnpUtil installation instead of wdreg
- Disable Control device, disable Selective suspend (can enable manually)
- Honeywell HH760 Area Imaging Scanner
- Xenon Charge & Communication Base
- Granit XP 1990i XLR Area-Imaging Scanner
- Granit XP 1991i XLR Area-Imaging Scanner
- Solaris 7990G Presentation Scanner
- Industrial Charge and Communication Base(CCB01)
- HH762 Cordless Scanner with base
- Honeywell HH180x

HSM USB Serial Driver Release 3.5.34 contains (November 2022):

- Driver Version 2.1.6.41
- Includes embedded VC++ 2010 Redistributable
- Microsoft Certified

Supporting devices:

- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)



- Voyager -1250
- Hyperion 1300
- Industrial Area -Imaging Scanner
- Industrial Charge & Communication Base (CCB02)
- Honeywell N5600 Series Area Image Engine (PID_0974 is added)
- Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300



- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBase
- CM5680SR
- CM3680SR
- CM2180MP



- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C
- Granit XP 1990iSR Area-Imaging Scanner
- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner
- Honeywell HF680
- Honeywell HH490 Hand-Held Scanner
- Genesis XP 7680GSR Presentation Scanner
- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)
- Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU)
- Honeywell HF521
- Honeywell LTSB N4680 (Win10 WHQL passed)
- Honeywell 20H2 N4680 (Win10 WHQL passed)
- Added Win7/8 versions supported, pnpUtil installation instead of wdreg



- Disable Control device, disable Selective suspend (can enable manually)
- Honeywell HH760 Area Imaging Scanner
- Xenon Charge & Communication Base
- Granit XP 1990i XLR Area-Imaging Scanner
- Granit XP 1991i XLR Area-Imaging Scanner
- Solaris 7990G Presentation Scanner
- Industrial Charge and Communication Base(CCB01)
- HH762 Cordless Scanner with base

=====

HSM USB Serial Driver Release 3.5.32 contains (August 2022):

- Driver Version 2.1.6.41
- Includes embedded VC++ 2010 Redistributable
- Microsoft Certified

Supporting devices:

- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)
- Voyager -1250
- Hyperion 1300
- Industrial Area -Imaging Scanner
- Industrial Charge & Communication Base (CCB02)
- Honeywell N5600 Series Area Image Engine (PID_0974 is added)
- Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,



MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos,
MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980
Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,
MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590
VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS

- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point



- Xenon HC Charge and Communication Base
- Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP



- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C
- Granit XP 1990iSR Area-Imaging Scanner
- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner
- Honeywell HF680
- Honeywell HH490 Hand-Held Scanner
- Genesis XP 7680GSR Presentation Scanner
- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)
- Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU)
- Honeywell HF521
- Honeywell LTSB N4680 (Win10 WHQL passed)
- Honeywell 20H2 N4680 (Win10 WHQL passed)
- Added Win7/8 versions supported, pnpUtil installation instead of wdreg
- Disable Control device, disable Selective suspend (can enable manually)
- Honeywell HH760 Area Imaging Scanner
- Xenon Charge & Communication Base
- Granit XP 1990i XLR Area-Imaging Scanner
- Granit XP 1991i XLR Area-Imaging Scanner
- Solaris 7990G Presentation Scanner

=====



HSM USB Serial Driver Release 3.5.30 contains:

- Driver Version 2.1.6.41
- Includes embedded VC++ 2010 Redistributable
- Microsoft Certified • Supporting devices:
 - Xenon 1900, Xenon 1902
 - Honeywell Access Point (HAP)
 - Voyager -1250
 - Hyperion 1300
 - Industrial Area -Imaging Scanner
 - Industrial Charge & Communication Base (CCB02)
 - Honeywell N5600 Series Area Image Engine (PID_0974 is added)
 - Voyager 1200
 - IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,



MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos,
MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980
Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,
MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590
VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS

- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager

3800i, 4800dr, QC890, 4206

5180 Area Imager

- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point



Xenon HC Charge and Communication Base

- Honeywell Access Point
- Voyager-CCB00-Battery-Free

Honeywell N3600 Series Area Image Engine

Voyager 1602g

- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470



- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C
- Granit XP 1990iSR Area-Imaging Scanner
- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner
- Honeywell HF680

Honeywell HH490 Hand-Held Scanner

Genesis XP 7680GSR Presentation Scanner

- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)
- Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU)
- Honeywell HF521
- Honeywell LTSB N4680 (Win10 WHQL passed)
- Honeywell 20H2 N4680 (Win10 WHQL passed)
- Added Win7/8 versions supported, pnpUtil installation instead of wdreg
- Disable Control device, disable Selective suspend (can enable manually)
- Honeywell HH760 Area Imaging Scanner
- Xenon Charge & Communication Base

HSM USB Serial Driver Release 3.5.29 – September 2021 contains:

- Driver Version 2.1.6.41



- Includes embedded VC++ 2010 Redistributable
- Microsoft Certified
- Supporting devices:
 - Xenon 1900, Xenon 1902
 - Honeywell Access Point (HAP)
- Voyager-1250
- Hyperion 1300
 - Industrial Area-Imaging Scanner
 - Industrial Charge & Communication Base (CCB02)
 - Honeywell N5600 Series Area Image Engine (PID_0974 is added)



Voyager 1200

- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40



- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded



- 1602 Honeywell Access Point
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C
- Granit XP 1990iSR Area-Imaging Scanner
- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner
- Honeywell HF680
- Honeywell HH490 Hand-Held Scanner
- Genesis XP 7680GSR Presentation Scanner
- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)
- Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU)
- Honeywell HF521
- Honeywell LTSB N4680 (Win10 WHQL passed) Honeywell 20H2 N4680 (Win10 WHQL passed)
Added Win7/8 versions supported, pnpUtil installation instead of wdreg.
Disable Control device, disable Selective suspend (can enable manually)



- Honeywell Ingenic Base

HSM USB Serial Driver Release 3.5.28 – July 2021 contains:

- Driver Version 2.1.6.41
- Includes embedded VC++ 2010 Redistributable
- Microsoft Certified
- **Supporting devices:**
 - Xenon 1900, Xenon 1902
 - Honeywell Access Point (HAP)
 - Voyager-1250
 - Hyperion 1300
 - Industrial Area-Imaging Scanner
 - Industrial Charge & Communication Base (CCB02)
 - Honeywell N5600 Series Area Image Engine (PID_0974 is added)
 - Voyager 1200
 - IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager
- 3800i, 4800dr, QC890, 4206



- 1602 Honeywell Access Point
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- Xenon HC Charge and Communication Base
- Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell



- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C



- 1602 Honeywell Access Point
- Granit XP 1990iSR Area-Imaging Scanner
- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner
- Honeywell HF680
- Honeywell HH490 Hand-Held Scanner
- Genesis XP 7680GSR Presentation Scanner
- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)
- Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU)
- Honeywell HF521
- Honeywell LTSB N4680 (Win10 WHQL passed)
- Honeywell 20H2 N4680 (Win10 WHQL passed)
- Added Win7/8 versions supported, pnpUtil installation instead of wdreg
- Disable Control device, disable Selective suspend (can enable manually)

HSM USB Serial Driver Release 3.5.27 – June 16th-2021 contains:

- Driver Version 2.1.6.41
 - Includes embedded VC++ 2010 Redistributable
- Microsoft Certified
- **Supporting devices:**
 -



- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)
- Voyager-1250
- Hyperion 1300
 - Industrial Area-Imaging Scanner
 - Industrial Charge & Communication Base (CCB02)
 - Honeywell N5600 Series Area Image Engine (PID_0974 is added)
- Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,
- Xenon HC Charge and Communication Base
 - MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700



- 1602 Honeywell Access Point
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBase
- CM5680SR



- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C
- Granit XP 1990iSR Area-Imaging Scanner
- Xenon HC Charge and Communication Base
- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner
- Honeywell HF680
- Honeywell HH490 Hand-Held Scanner
- Genesis XP 7680GSR Presentation Scanner
- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)
- Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU)



- 1602 Honeywell Access Point

Honeywell HF521

- Honeywell LTSB N4680 (Win10 WHQL passed)
HSM USB Serial Driver Release 3.5.26 – June-2021 contains:
- Driver Version 2.1.9.1
 - Includes embedded VC++ 2010 Redistributable
- Microsoft Certified
- Supporting devices:
 - Xenon 1900, Xenon 1902
 - Honeywell Access Point (HAP)
- Voyager-1250
- Hyperion 1300
 - Industrial Area-Imaging Scanner
 - Industrial Charge & Communication Base (CCB02)
 - Honeywell N5600 Series Area Image Engine (PID_0974 is added)
- Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,
 - MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager



- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Xenon HC Charge and Communication Base
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g



- 1602 Honeywell Access Point
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C
- Granit XP 1990iSR Area-Imaging Scanner



- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner
- Honeywell HF680
- Honeywell HH490 Hand-Held Scanner
- Genesis XP 7680GSR Presentation Scanner
- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)
- Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU) Honeywell HF521

HSM USB Serial Driver Release 3.5.25 – April-2021 contains:

- Driver Version 2.1.9.1
- Includes embedded VC++ 2010 Redistributable
- Microsoft Certified

Supporting devices:

- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)
- Voyager-1250
- Hyperion 1300
- Industrial Area-Imaging Scanner
- Industrial Charge & Communication Base (CCB02)
- Honeywell N5600 Series Area Image Engine (PID_0974 is added)
- Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos,



- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
 - MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980
 - Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i



- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBase
- CM5680SR
- CM3680SR
- CM2180MP

Industrial Area-



Imaging Scanner 1920i

Xenon Power Corded


- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C
- Granit XP 1990iSR Area-Imaging Scanner
- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner
- Honeywell HF680
- Honeywell HH490 Hand-Held Scanner
- Genesis XP 7680GSR Presentation Scanner
- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)
Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU)



HSM USB Serial Driver Release 3.5.24 – March-2021 contains:

- Driver Version 2.1.9.1
 - Includes embedded VC++ 2010 Redistributable
- Microsoft Certified

- Supporting devices:
 - Xenon 1900, Xenon 1902
 - Honeywell Access Point (HAP)
- Voyager-1250
- Hyperion 1300
 - Industrial Area-Imaging Scanner
 - Industrial Charge & Communication Base (CCB02)
 - Honeywell N5600 Series Area Image Engine (PID_0974 is added)
- Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices)
 - 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700

- Laser  Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i



- Xenon HC Charge and Communication Base
- Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner

- Airline  Xenon XP

- Xenon Power Lite Corded – 1900-C

- Xenon Power Lite Corded Healthcare– 1900h-C

- Xenon Power Lite Cordless – 1902-C

Granit XP 1990iSR Area-Imaging Scanner

Granit XP 1991iSR Area-Imaging Scanner

- Granit XP 1990iXR Area-Imaging Scanner

- Granit XP 1991iXR Area-Imaging Scanner

- Honeywell HF680

- Honeywell HH490 Hand-Held Scanner

- Genesis XP 7680GSR Presentation Scanner

- Honeywell 1350g Hand-Held Scanner (HH490 for US and EU regions)

- Honeywell OH460 Hand-Held Scanner (HH490 Chinese online SKU) • 1602 Honeywell Access Point

HSM USB Serial Driver Release 3.5.23 – Jan-2021 contains: • Driver
Version 2.1.9.1

•Includes embedded VC++ 2010 Redistributable

- Microsoft Certified

- Supporting devices:

•Xenon 1900, Xenon 1902

•Honeywell Access Point (HAP)

- Voyager-1250

- Hyperion 1300

•Industrial Area-Imaging Scanner

•Industrial Charge & Communication Base (CCB02)

•Honeywell N5600 Series Area Image Engine (PID_0974 is added)

- Voyager 1200

- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices)
5110
Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB



Granit 1980i



Xenon HC Charge and Communication Base

Honeywell Access Point

•	Voyager-CCB00-Battery-Free	
•	Honeywell N3600 Series Area Image Engine	
•	Voyager 1602g	
•	Xenon 1900hc Area-Imaging Scanner	
•	Solaris 7980 Area-Imaging Scanner Honeywell	
•	N660X Series Area Image Engine	
•	1452 Honeywell Access Point	
•	Orbit 7190g Hybrid Scanner	
•	Orbit 7120plus Hybrid Scanner	
•	XenonBFBase	
•	CM5680SR	
•	CM3680SR	
•	CM2180MP	
•	Industrial Area-Imaging Scanner 1920i	
•	Xenon Power Corded	
•	Xenon Power cordless- Battery Free	
•	Xenon Power cordless with Battery-1952g	
•	Voyager Power Corded -1470	
• •	Xenon Power Lite Corded – 1900-----	11
•	Xenon Power Lite Corded Healthcare– 1900h -----	11
•	Xenon Power Lite Cordless – 1902 -----	11

- Voyager XP1472g Area-Imaging Scanner

- Airline Xenon XP

- Granit XP 1990iSR Area-Imaging Scanner

- Granit XP 1991iSR Area-Imaging Scanner

- Granit XP 1990iXR Area-Imaging Scanner

- Granit XP 1991iXR Area-Imaging Scanner

- Honeywell HF680

- Honeywell HH490 Hand-Held Scanner

- 1602 Honeywell Access Point

HSM USB Serial Driver Release 3.5.22 – 08/10/2020 contains:

- Driver Version 2.1.9.1

- Includes embedded VC++ 2010 Redistributable

- Microsoft Certified

- Supporting devices:

- Xenon 1900, Xenon 1902

- Honeywell Access Point (HAP)

- Voyager-1250

- Hyperion 1300

- Industrial Area-Imaging Scanner

- Industrial Charge & Communication Base (CCB02)

- Honeywell N5600 Series Area Image Engine (PID_0974 is added)

- Voyager 1200

- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691

FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600



- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager

- 3800i, 4800dr, QC890, 4206

- 5180 Area Imager

- 4600g, 4800p, 3800g

- 33xx Area-Imaging Scanner

- Voyager-CCB00

- Honeywell N8600 Series Area Image Engine

- Voyager 1400g Series • Stratos 2700

Laser Engine-N4300

- Genesis 7580 Area-Imaging Scanner

- 4850DR Document Imager

- ED40

- Voyager 1450g

- 14XX Charge & Communication Base

- Granit 1981i CCB

- Granit 1980i

-

-

-

-

Xenon HC Charge and Communication Base

Honeywell Access Point

Voyager-CCB00-Battery-Free

- Honeywell N3600 Series Area Image Engine

Voyager 1602g

- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free



- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner

Airline Xenon XP

- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C
- Granit XP 1990iSR Area-Imaging Scanner
- Granit XP 1991iSR Area-Imaging Scanner
- Granit XP 1990iXR Area-Imaging Scanner
- Granit XP 1991iXR Area-Imaging Scanner

•

•

- Honeywell HF680

HSM USB Serial Driver Release 3.5.21 – 11/07/2019 contains:

- Driver Version 2.1.9.1
- Includes embedded VC++ 2010 Redistributable
- Microsoft Certified • Supporting devices:



-
-
-
- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)
- Voyager-1250
- Hyperion 1300
- Industrial Area-Imaging Scanner

Industrial Charge & Communication Base (CCB02)

Honeywell N5600 Series Area Image Engine (PID_0974 is added) • Voyager 1200

- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager



- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i

•

- 1602 Honeywell Access Point

•

1981 Honeywell Access

Xenon HC Charge and Communication Base



Point

- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C



- Granit XP 1990iSR Area-Imaging Scanner
- Granit XP 1991iSR Area-Imaging Scanner

HSM USB Serial Driver Release 3.5.20 – 10/14/2019 contains:

- Driver Version 2.1.9.1
- Includes embedded VC++ 2010 Redistributable
- Microsoft Certified • Supporting devices:
 - Xenon 1900, Xenon 1902
 - Honeywell Access Point (HAP)
 - Voyager-1250
 - Hyperion 1300
 - Industrial Area-Imaging Scanner
 - Industrial Charge & Communication Base (CCB02)
 - Honeywell N5600 Series Area Image Engine (PID_0974 is added) • Voyager 1200 IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus,
 - MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600
 - Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,
 - MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos,
 - MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980
 - Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590
 - VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
 - MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager
 - 3800i, 4800dr, QC890, 4206
 - 5180 Area Imager
 - 4600 g, 4800p, 3800g
 - 33xx Area-Imaging Scanner
 - Voyager-CCB00 Honeywell N8600 Series Area
 - Image Engine



- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner Honeywell
- N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470



- Voyager XP1472g Area-Imaging Scanner
- Airline Xenon XP
- Xenon Power Lite Corded – 1900-C
- Xenon Power Lite Corded Healthcare– 1900h-C
- Xenon Power Lite Cordless – 1902-C

HSM USB Serial Driver Release 3.5.18 – 07/25/2019 contains:

D
r
i
v
e
r
V
e
r
s
i
o
n
2
.
1
.
9
.
1

- Includes embedded VC++ 2010 Redistributable

- Microsoft Certified • Supporting devices:
- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)



- Voyager-1250
- Hyperion 1300
- Industrial Area-Imaging Scanner
- Industrial Charge & Communication Base (CCB02)
- Honeywell N5600 Series Area Image Engine (PID_0974 is added) • Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus,
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager- CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i



- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- 1981 Honeywell
- Access Point
- Voyager -CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area -Imaging Scanner Solaris
 - 7980 Area-Imaging Scanner Honeywell
 - N660X Series Area Image Engine
 - 1452 Honeywell Access Point Orbit 7190g Hybrid Scanner Orbit 7120plus Hybrid Scanner
 - XenonBFBase
 - CM5680SR
 - CM3680SR
 - CM2180MP
- Industrial Area-Imaging Scanner 1920i
- Xenon Power Corded
- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery- Voyager Power Corded -1470 Voyager
 - 1952g XP1472g Area-Imaging Scanner
- Airline Xenon XP

HSM USB Serial Driver Release 3.5.17 – 07/08/2019 contains:

- Driver Version 2.1.9.1
- Includes embedded VC++ 2010 Redistributable
- Supporting devices:



- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP) Voyager-1250
- Hyperion 1300
- Industrial Area-Imaging Scanner
- Industrial Charge & Communication Base (CCB02)
- Honeywell N5600 Series Area Image Engine (PID_0974 is added) • Voyager
1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus,
MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris,
MS7600
Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,
MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431
Stratos,
MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980
Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540
VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS,
MS9590i VoyagerGS, MS9591i
VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for
both devices) □ 5110 Area Imager
- 3800i, 4800dr, QC890, 4206



- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series Stratos 2700 Laser Engine-N4300 Genesis 7580
AreaImaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base Granit 1981i CCB
Granit 1980i
1602 Honeywell Access Point
- Xenon 1900hc Area-Imaging Scanner Solaris
7980 Area-Imaging Scanner Honeywell
N660X Series Area Image Engine 1452
Honeywell Access Point

Orbit 7190g Hybrid Scanner
Orbit 7120plus Hybrid Scanner

XenonBFBase

CM5680SR



CM3680SR

CM2180MP

Industrial Area-Imaging Scanner 1920i

Xenon Power Corded

- Xenon Power cordless- Battery Free
- Xenon Power cordless with Battery-1952g
- Voyager Power Corded -1470
- Voyager XP1472g Area-Imaging Scanner

HSM USB Serial Driver Release 3.5.15 – 04/30/2019 contains:

Driver Version 2.1.9.1

- Includes embedded VC++ 2010 Redistributable
- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices:
- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)
- Voyager-1250
- Hyperion 1300
- Industrial Area-Imaging Scanner
- Industrial Charge & Communication Base (CCB02)
- Honeywell N5600 Series Area Image Engine (PID_0974 is added) • Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,



MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos,
MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980

Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,

MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i
VoyagerGS, MS9591i VoyagerGS

- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom
firmware for both devices) □ 5110 Area

Imager

- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base



• •

• •

•

- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner
- Honeywell N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBase
- CM5680SR
- CM3680SR
- CM2180MP
 - Industrial Area-Imaging Scanner 1920i
 - Voyager Upgrade



Xenon Power Corded

HSM USB Serial Driver Release 3.5.9 – 06/13/2017 contains:

- Driver Version 2.1.9.1
- Includes embedded VC++ 2010 Redistributable
- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices:

Xenon 1900, Xenon 1902

Honeywell Access Point (HAP)

Voyager-1250

Hyperion 1300

Industrial Area-Imaging Scanner

Industrial Charge & Communication Base (CCB02)

Honeywell N5600 Series Area Image Engine (PID_0974 is added) Voyager 1200 •

IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600

Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,

MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS

• MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) □ 5110 Area Imager

- 3800 i, 4800dr, QC890, 4206
- 5180 Area Imager • 4600g, 4800p, 3800g



• •

• •

- 33xx Area-Imaging Scanner Voyager-CCB00

Honeywell N8600 Series Area Image Engine

Voyager 1400g Series

Stratos 2700

-
-
-

Laser Engine-N4300

-

Genesis 7580 Area-Imaging Scanner

4850DR Document Imager ED40

-

- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base

1981 Honeywell Access Point

- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g



- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner
- Honeywell N660X Series Area Image Engine
- 1452 Honeywell Access Point
- Orbit 7190g Hybrid Scanner
- Orbit 7120plus Hybrid Scanner
- XenonBFBBase
- CM5680SR
- CM3680SR
- CM2180MP
- Industrial Area-Imaging Scanner 1920i

Disclaimer for HSM USB Serial Driver 3.5.9

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable ScannerScale protocols (NCR,etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance

HSM USB Serial Driver Release 3.5.7 – 05/24/2016 contains:

- Driver Version 2.1.9.1
- Includes embedded VC++ 2010 Redistributable
- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices:
- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)
- Voyager-1250
- Hyperion 1300



• •

• •

•

- Industrial Area-Imaging Scanner
- Industrial Charge & Communication Base (CCB02)
- Honeywell N5600 Series Area Image Engine (PID_0974 is added) • Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) □ 5110 Area Imager
3800i, 4800dr, QC890, 4206
5180 Area Imager
4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
-
-
-
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager



- ED40
- Voyager 1450g
-
- 14XX Charge & Communication Base Granit 1981i CCB Granit
1980i
1602 Honeywell Access Point
Xenon HC Charge and Communication Base
1981 Honeywell Access Point
Voyager-CCB00-Battery-Free
Honeywell N3600 Series Area Image Engine
Voyager 1602g
Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner
Honeywell N660X Series Area Image Engine
- 1452 Honeywell Access Point

Disclaimer for HSM USB Serial Driver 3.5.7

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable Scanner-Scale protocols (NCR,etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance



• •

• •

•

HSM USB Serial Driver Release 3.5.5 – 04/01/2016 contains:

- Driver Version 2.1.9.1
- Add Silent Install support
- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices: Xenon 1900, Xenon 1902

Honeywell Access Point (HAP)

Voyager-1250

Hyperion 1300

Industrial Area-Imaging Scanner

Industrial Charge & Communication Base (CCB02)

Honeywell N5600 Series Area Image Engine (PID_0974 is added) Voyager 1200

IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus,

MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon,
MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,

MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320
StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980

Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,

MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590

VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS

- MS4980 Vuquest,
MS7580 Genesis

(NOTE:

supports PID 0731 only,

which requires custom firmware for both devices) □ 5110 Area Imager

- 3800i, 4800dr, QC890, 4206

- 5180 Area Imager



- [illegible]



4850DR Document Imager ED40

Voyager 1450g

14XX Charge & Communication Base

- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
 - Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner
- Honeywell N660X Series Area Image Engine
 - 1452 Honeywell Access Point

Disclaimer for HSM USB Serial Driver 3.5.5

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable ScannerScale protocols (NCR,etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance

•

•

•

•

HSM USB Serial Driver Release 3.5.3 – 01/25/2016 contains:

- Driver Version 2.1.9.1



- Driver package: Windows Hardware Quality Labs (WHQL)
Certified. Supporting devices: Xenon
1900, Xenon 1902

Honeywell Access Point (HAP) Voyager-1250

Hyperion 1300

Industrial Area-Imaging Scanner

Industrial Charge & Communication Base (CCB02)

Honeywell N5600 Series Area Image Engine (PID_0974 is added) Voyager 1200

IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus,

MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600

Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,

MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos,

MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE,

MS4980

Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,

MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590
VoyagerGS,

MS9590i VoyagerGS, MS9591i VoyagerGS

- MS4980 Vuquest, MS7580 Genesis
(NOTE: supports PID 0731 only, which requires custom firmware for both devices) □ 5110 Area
Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series



- Stratos 2700

Laser Engine-N4300

Genesis 7580 Area-Imaging Scanner

- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner
- Honeywell N660X Series Area Image Engine
- Xenon 1850g



Disclaimer for HSM USB Serial Driver 3.5.3

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable Scanner-Scale protocols (NCR,etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance

HSM USB Serial Driver Release 3.5.1 – 10/20/2015 contains:

- Driver Version 2.1.9.1
- Add Windows 10 WHQL certification support. Please see the “Supported



Operating Systems” section at the end of this Release Notes for a complete list of

supported
OS.

- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices:
 -
- Xenon 1900, Xenon 1902 □
- Honeywell Access Point (HAP) • Voyager-1250 Hyperion 1300 Industrial Area-Imaging Scanner

Industrial Charge & Communication Base (CCB02)

Honeywell N5600 Series Area Image Engine (PID_0974 is added) Voyager 1200 • IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus,

MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600



Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS

- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) □ 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner
- Solaris 7980 Area-Imaging Scanner
- Honeywell N660X Series Area Image Engine



Disclaimer for HSM USB Serial Driver 3.5.1

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable Scanner-Scale protocols (NCR, etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance



HSM USB Serial Driver Release 3.4.15 – 09/24/2015 contains:

- Driver Version 2.1.9.1
- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices:
- Xenon 1900, Xenon 1902 Honeywell Access Point (HAP) Voyager-1250


Hyperion 1300



Industrial Area- Imaging Scanner

Industrial
Charge &

N5600 Series Area Image Engine



Communication Base (CCB02) Honeywell
(PID_0974 is

IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS

- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) 5110 Area Imager □
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner



- Solaris 7980 Area-Imaging Scanner
- N660X Mini DB

Disclaimer for HSM USB Serial Driver 3.4.15

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single

Cable Scanner -Scale
Not On Industrial Area-
Industrial Charge &
protocols (NCR,etc...),
ACK-NAK
Imaging Scanner
added)
Voyager 1200 S
Communication Base (CCB02) Honeywell N5600 Series Area Image
Engine (PID_0974 is

File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance

Honeywell

HSM USB Serial Driver Release 3.4.13 – 08/05/2015 contains:

- Driver Version 2.1.9.1

- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices: Xenon 1900, Xenon 1902

Honeywell Access Point (HAP)

Voyager-1250

Hyperion 1300

IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS


- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) □ 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- 33xx Area-Imaging Scanner
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g

- 14XX Charge & Communication Base
- Granit 1981i CCB

- Granit 1980i
- 1602 Honeywell Access Point



- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free
- Honeywell N3600 Series Area Image Engine
- Voyager 1602g
- Xenon 1900hc Area-Imaging



Disclaimer for HSM USB Serial Driver 3.4.13

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable Scanner-Scale protocols (NCR,etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance HSM USB Serial Driver Release 3.4.11 – 06/18/2015 contains:

- Driver Version 2.1.9.1
- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices: Xenon 1900, Xenon 1902

Honeywell Access Point (HAP)
Voyager-1250

Hyperion 1300

Honeywell

1

□

5

1

1

□

Industrial Charge &

Honeywell N5600 Series Area Image Engine (PID_0974 is added) Voyager 1200

IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus,

MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820
Solaris, MS7600

Horizon,

MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,
MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431

Stratos,

MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980

Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521

Voyager,

MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS,
MS9590i VoyagerGS, MS9591i VoyagerGS

- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) □ 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- Vuquest 3310
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager
- ED40
- Voyager 1450g

- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free



- Honeywell N3600 Series Area Image Engine

- Voyager 1602g
- Xenon 1900hc Area-Imaging Scanner

Disclaimer for HSM USB Serial Driver 3.4.11

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single

Cable Scanner-Scale protocols (NCR,etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance



Driver Release 3.4.9

– 02/19/2015 contains:

- Driver Version

2.1.9.1

- Driver package:

Windows

Hardware Quality Labs (WHQL) Certified. Supporting devices:



Xenon 1900, Xenon 1902

Honeywell Access Point (HAP)

Voyager-1250

Hyperion 1300

Industrial Area-Imaging Scanner

Industrial Charge & Communication Base (CCB02)

Honeywell N5600 Series Area Image Engine (PID_0974 is added) Voyager 1200

IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600 Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion, MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager, MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS

- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices)

□

- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- Vuquest 3310

□ • Voyager-CCB00

- Honeywell N8600 Series Area Image Engine




- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner



- 4850DR Document Imager
- ED40
- Voyager 1450g
- 14XX Charge & Communication Base
- Granit 1981i CCB
- Granit 1980i
- 1602 Honeywell Access Point
- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free
- For all other HSM devices, please continue to use the HSM USB Serial Driver version 1.19

Disclaimer for HSM USB Serial Driver 3.4.9





At this time support is generally limited to barcode  data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable Scanner-Scale protocols (NCR, etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance

HSM USB Serial Driver Release 3.4.8 – 01/07/2015 contains:

- Driver Version 2.1.9.1
- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices:
- Xenon 1900, Xenon 1902 Honeywell Access Point (HAP)

Voyager-1250

 Hyperion 1300 

Industrial Area-Imaging Scanner



Industrial

Charge & Communication Base (CCB02)

Honeywell N5600 Series Area Image Engine (PID_0974 is added) Voyager 1200 •
IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690
Focus, MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris,

MS7600

Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,
MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos,
MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980
Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,
MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590
VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS

MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both
devices) □ 5110 Area Imager

3800i, 4800dr, QC890, 4206

5180 Area Imager

4600g, 4800p, 3800g

Vuquest 3310

Voyager-CCB00

Honeywell N8600 Series Area Image

Engine

Voyager 1400g Series

Stratos 2700

Laser Engine-N4300

- Genesis 7580 Area-Imaging Scanner
- Granit 1450g
- Voyager-CCB Document Imager
- 14XX Charge & Communication Base
- Honeywell Access Point
- ED40
- Xenon HC Charge and Communication Base
- 1981 Honeywell Access Point
- Voyager-CCB00-Battery-Free
- For all other HSM devices, please continue to use the HSM USB
Serial Driver version 1.19

Disclaimer for HSM USB Serial Driver 3.4.8

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable Scanner-Scale protocols (NCR,etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance

HSM USB Serial Driver Release 3.4.6 – 12/01/2014 contains:

- Driver Version 2.1.9.1
- Driver package: Windows Hardware
- Quality Labs (WHQL)
Certified. Supporting devices: Xenon
1900,
Xenon 1902
- Honeywell Access Point (HAP) Voyager-1250
- 14XX Charge & Communication Base Granit 1981i CCB

- Xenon HC Charge and Communication



- 1981 Honeywell

- ..

Industrial Charge &

MS7600

- Hyperion 1300
- Industrial Area-Imaging Scanner
- Communication Base (CCB02) Honeywell N5600 Series Area Image Engine
- (PID_0974 is added) Voyager 1200 IS4823 Microquest Decode, IS4920
- Vuquest, Access Point, MS1690 Focus,
- MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris,
- Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,
- MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos,
- MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980
- Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,
- MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS, MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) □ 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- •
- Vuquest 3310

Honeywell

□

□

□

□

□

□

-
-
-
-
-
- process. Note that embedded firmware and hardware upgrades
-
-
- version
 - For all other HSM devices, please continue to use the HSM USB Serial Driver
-
- 1.19
-
- MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600
- Horizon, MS3580 QuantumT, MS7120 Orbit,
- MS7180
- OrbitCG,
- MS3780
-
- Disclaimer for HSM USB Serial Driver 3.4.6 Not
- On
- At this time support is generally limited to barcode data for the Stratos File 2300/2400 product family. Features that need incremental embedded Messages, firmware to support for virtual communication port features like Single and others
-
- will need
- Cable Scanner-Scale protocols (NCR,etc...), ACK-NAK handshaking,
- Engine (PID_0974 is added) Voyager 1200 to be added via
-

- Access Point, IS4823 Microquest Decode, IS4920 Vuquest, the
- standard
- MS1690 Focus, EWR
-
- Industrial Area- may
- Imaging Scanner also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance HSM USB Serial Driver
- Release 3.4.2 – 10/23/2014 contains: • Driver Version 2.1.9.1
-
- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices:
- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP) • Voyager-1250 Hyperion 1300 \
- MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos, Fusion, MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980 Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,
- MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS,
- MS9590i VoyagerGS, MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) □ 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- Vuquest 3310
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700
- Laser Engine-N4300

- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager ED40
- Voyager 1450g

For all other HSM devices, please continue to use the HSM USB Serial Driver version 1.19

Disclaimer for HSM USB Serial Driver 3.4.2

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable Scanner-Scale protocols (NCR,etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance

HSM USB Serial Driver Release 3.1.4 – 5/23/2014 contains:

- Driver Version 2.1.9.1
- Driver package: Windows Hardware Quality Labs (WHQL) Certified. Supporting devices:
- Xenon 1900, Xenon 1902
- Honeywell Access Point (HAP)
- Voyager-1250
- Hyperion 1300
- Industrial Area-Imaging Scanner
- Industrial Charge & Communication Base (CCB02)
- Honeywell N5600 Series Area Image Engine (PID_0974 is added) Voyager 1200
- IS4823 Microquest Decode, IS4920 Vuquest, Access Point, MS1690 Focus,
- MS1691 FocusHD, MS1633 FocusBT, MS5145 Eclipse, MS7820 Solaris, MS7600
- Horizon, MS3580 QuantumT, MS7120 Orbit, MS7180 OrbitCG, MS3780 Fusion,
- MS2420 Stratos, MS2421 Stratos, MS2422 Stratos, MS2430 Stratos, MS2431 Stratos,
- MS2320 StratosH, MS2321 StratosH, MS2322 StratosH, MS2122 StratosE, MS4980
- Vuquest, MS4984 Vuquest, MS7580 Genesis, MS9520 Voyager, MS9521 Voyager,
- MS9540 VoyagerCG, MS9541 VoyagerCG, MS9535 VoyagerBT, MS9590 VoyagerGS,
- MS9590i VoyagerGS,
- MS9591i VoyagerGS
- MS4980 Vuquest, MS7580 Genesis (NOTE: supports PID 0731 only, which requires custom firmware for both devices) □
- 5110 Area Imager
- 3800i, 4800dr, QC890, 4206
- 5180 Area Imager
- 4600g, 4800p, 3800g
- Vuquest 3310
- Voyager-CCB00
- Honeywell N8600 Series Area Image Engine
- Voyager 1400g Series
- Stratos 2700

- Laser Engine-N4300
- Genesis 7580 Area-Imaging Scanner
- 4850DR Document Imager ED40
- For all other HSM devices, please continue to use the HSM USB Serial Driver version 1.19

Disclaimer for HSM USB Serial Driver 3.1.4

At this time support is generally limited to barcode data for the Stratos 2300/2400 product family. Features that need incremental embedded firmware to support for virtual communication port features like Single Cable Scanner-Scale protocols (NCR,etc...), ACK-NAK handshaking, Not On File Messages, and others will need to be added via the standard EWR process. Note that embedded firmware and hardware upgrades may also be required. Please consult your Honeywell Scanning & Mobility representative for further guidance

Summary

The Honeywell Scanning & Mobility (HSM) USB Serial Driver is a CDC ACM driver that exposes HSM USB scanners as as a virtual COM port to the operating system and applications. This document covers the following topics relating to the HSM USB Serial Driver:

- Supported Operating Systems
- Enhancements and Bug Fixes
- Known Issues

Supported Operating Systems

The following operating systems are supported with this driver:

- Windows 11 – 64bit
- Windows 10 – 32 bit and 64 bit
- Windows 8.1 – 32 bit and 64 bit
- Windows 8 – 32 bit and 64 bit
- Windows 7 – 32 bit and 64 bit
- Windows XP – 32 bit and 64 bit
- Windows Vista – 32 bit and 64 bit
- Windows Embedded Point of Service (WEPOS 1.x)
- Windows Embedded POSReady 2009
- Windows Embedded POSReady 7
- Windows Embedded 8 Industry
- Windows Embedded 8.1 Industry
- Windows 10 IoT Enterprise LTSC 2015

Enhancements and Bug Fixes

None

Known Issues

- When Force COM port feature is enabled, the friendly name found in device manager->ports does not have the (COM#) suffix immediately after installation. However, it does get added on next driver start.

- Blue screen may occur on some devices using Windows XP SP2 when coming out of suspend mode. This can be fixed by Windows XP SP3 or Windows Hot Fix 949483. <http://support.microsoft.com/hotfix/KBHotfix.aspx?kbnum=949483&kbln=en-us>

- Known differences between legacy Hand Held Products COM Em driver (hhpcdc.sys) and Honeywell Scanning & Mobility (HSM) USB Serial Driver:

- oThe Registry name under [HKLM \HARDWARE\DEVICEMAP\SERIALCOMM]\Device\ is different from the legacy driver.

The old name is “HhpcdcVirtualPortx.” The new name is “honeywell_cdc_AcmSerialx.”

- Applications will NOT receive a WM_DEVICECHANGE notification. The driver emulates a serial COM port, which exists in the system even when the USB device has been detached. However, there is an open handle to this device. This is the difference between the legacy Hand Held Products driver and the new driver. The WM_DEVICECHANGE notification is received from the DeviceManager when a device is created/removed. Because the device is not removed, the WM_DEVICECHANGE